Wingham Parish Council Highway Improvement Plan Summary for the Parish Council website February 2022

HIGHW	VAY IMPROVEMEN	IT PLAN	ACTION PLAN
Priority	Location	Problem and suggested remedy by WPC	Comments and actions taken so far
1	A257 Gobery Hill, junction with Wildlife Park & Roman Road	Problem: Speeding; overtaking; hazardous pedestrian access to Wildlife Park & bus stops; overgrown vegetation on footway. Remedy : Buffer zone; widen road at park for central reservation & possible slip road; central double white lines; improve signs to indicate exits; more regular vegetation clearance.	KCC Officer investigated: potential s106 improvements; potential bus stop improvements; hedge maintenance. A257 Traffic Group met with Kent Police to discuss speed enforcement on the Roman Road. Speed checks carried out by Kent Police. Meeting organised end February 2022 to discuss and agree way forward.
2	Preston Hill junction with A257 High Street	Problem: Peak time congestion; speeding; Large vehicles mount island + pavements; hazardous for pedestrians Remedy: Re-model junction: reduce island size; increase width of footway o/s 113-114 High St; install triangular pinch to slow down/guide vehicles entering Preston Hill.	KCC working with WPC on design for junction to potentially include parking restrictions. Further work and consultation required.
3	A257 Canterbury Rd between Willow Cottage & bus stop at Mill Rd	Problem: Footpath on one side only; hazardous for pedestrians; overgrown vegetation. Remedy: Install new footpath; regular vegetation clearance.	Previous requests made for footpath 2014 & 2015. KCC drew up designs 2016 & consulted but funding not secured. Resident petition supported by WPC submitted to KCC Feb 2020, but rejected by KCC. KCC estimate costs to install footpath £24,000 based on KCC 2016 design. KCC to investigate utility services.
4	Watercress Lane	Problem: Diverted traffic from works elsewhere (B2046, etc) use this lane in error; Speeding; hazardous for residents; no footway. Remedy : Ensure Watercress Lane is not used during traffic diversions; traffic calming and/or signs to state no footway and protect residents.	KCC officer to raise this with the Streetworks Team to ensure appropriate signage used so that Watercress Lane should not be used when a diversion is in place. KCC have agreed to fund (in new financial year) edge of carriageway markings along the extent of houses fronting the carriageway.

Previous HIP Priorities removed at 25.1.22 meeting

Wingham High Street	Speeding/high volume of traffic; HGVs causing	20mph zone due to be completed February 2022
	vibrations; unsafe for pedestrians.	
C'bury Rd j/w Wingham High	Speeding traffic entering village from the South	20mph zone due to be completed February 2022
St; B2046 to Seath's Corner.	along B2046; property damage; large vehicles	
	unable to pass; hazardous for pedestrians.	
A257 Canterbury Rd	Inadequate fencing; subsiding bridge; damage	KCC have identified a scheme to make the bridge and carriageway safe. Work to commence
Wingham Bridge	to footway & carriageway	soon.
Preston Hill: Wenderton	Speeding traffic in both directions; hazardous	Reduce a section of NSL to 40mph to create a buffer zone when entering the existing 30mph.
Lane junction to just after	for pedestrians & residents.	Work due to be completed February 2022
Ashen Tree Cottages		

NB. HIP updated annually with KCC Highways. Last update: 25.01.2022